


■全体図(単位mm) (1/150)



■作業範囲図

▣ジブ装着 (オフセット角度10°/30°)

